


THERMOGRAPHIC INSPECTION



DATE: 9/2/2010

JOB #: 1575-M1

PICTURE #: 13

ITEM: Freezer Door




Label	Value
SP01	47.8°F
SP02	42.1°F

Emissivity	0.95
Object Distance	20.0 ft
Ambient Temp.	44.0°F
Imager Model	AGEMA 550 NTSC

CORRECTIVE ACTION TAKEN: _____

DATE: _____ SIGNATURE: _____

THERMOGRAPHIC INSPECTION



DATE: 9/2/2010

JOB #: 1575-M1

PICTURE #: 14

ITEM: Freezer Door



Label	Value
SP01	47.2°F
SP02	37.4°F
SP03	41.6°F

Emissivity	0.95
Object Distance	20.0 ft
Ambient Temp.	44.0°F
Imager Model	AGEMA 550 NTSC

CORRECTIVE ACTION TAKEN: _____

DATE: _____ SIGNATURE: _____